

1 insert gm card into **card slot** of Tech2




2


Connect self-test adapter with Tech2, then power on machine




3 Enter Main menu then choose F4: tool options




4 Choose F3: SELF-TEST




5 Press "Exist" to continue



6 Choose Tech 2 self-test



7 Automated VCI



8 VCI self-test result

